


Profile



© 2000 National Coatings Corporation.
All Rights Reserved. CH-ARS-006 11-01

SEARS WAREHOUSE

Size: 100,000 Square Feet

Location: Vernon, California

Challenge *Leaking & Corroding Metal Roof*

- Leaks at seams & fasteners.
- Mounting surface corrosion.
- Uncomfortable warehouse during summer.

Solution *AcryShield® Restoration System*

- Rust-inhibitive primer system.
- Reinforced seams & fasteners.
- Reduced summertime surface temperatures by 50°F.

Sears chose a Cool Roof restoration system to solve typical metal roof leak problems and to eliminate excess heat stress due to the intrinsic low heat release properties of bare metal and aluminum coated roofs.



(800)423-9557, www.nationalcoatings.com