

*Profile*

# Sequoia Pacific Systems

*Size: 340,000 Square Feet*

*Location: Exeter, California*



## **Challenge** *SBS Mod Bit Blistering*

- Severe membrane blistering and ridging.
- Ongoing thermal shock and stress.
- Major leak repairs expected.

## **Solution** *AcryShield® Restoration System*

- Reinforced blister repairs.
- No excess thermal shock.
- 10-15% energy savings.
- Avoided re-roof and saved valuable insulation.

*Sequoia Pacific restored a “terminally-ill” roof and now benefits from tens of thousands of dollars in lower energy bills without incurring the capital expense of a major re-roof project.*

© 2000 National Coatings Corporation.  
All Rights Reserved. CH-ARS-001 06-01



*(800)423-9557, [www.nationalcoatings.com](http://www.nationalcoatings.com)*